

Report of Bacteriological Analysis of Water / Effluent sample

Principal, Poornaprajna Education Centre, Lower Hutha, Bhadravathi -577301	Opinion							
	Sample No.	Source & Particulars of Water Sample	M. P. N. Count	Plate Count	D. C Test	S. P. P	N. S. P. P	N. S. P. P & FC
Note: M.P.N Count: Most probable number of Bacteria per 100 ml of water. D.C Test: Differential Coliform test Plate Count: Plate Count per ml of Sample SPP : Water is satisfactory for Potable Purpose NSPP : Water is not satisfactory for Drinking purpose NSPP & FC: Water is not satisfactory for Drinking purpose & E.Coli found	28	Tap water	-	-	(-)	SPP	-	-
	29	Bore well Tap water	-	-	-	SPP	-	-

PRINCIPAL
Poorna Prajna Education Centre
Lower Hutha, BHADRAVATHI
(08282) 866244

Secretary
Poornaprajna Education Centre
Lower Hutha, B.H. Road
BHADRAVATHI-577 301

ವೈದ್ಯಾಧಿಕಾರಿಗಳು
ನಗರ ಆರೋಗ್ಯ ಕೇಂದ್ರ
ಜನ್ನಪುರ. ಭದ್ರಾವತಿ

Medical Officer
City Health Centre
Jannapura, Bhadravathi